


N65928.AR.000951  
NTC ORLANDO  
5090.3a

LETTER REGARDING REGULATORY REVIEW AND COMMENTS ON SOURCE REMOVAL  
FOR BUILDING 7107 NTC ORLANDO FL  
10/6/1999  
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



# Department of Environmental Protection

Jeb Bush  
Governor

Twin Towers Building  
2600 Blair Stone Road  
Tallahassee, Florida 32399-2400

David B. Struhs  
Secretary

October 6, 1999

Mr. Nick Ugolini  
Code 1843 (UST RPM)  
Southern Division  
Naval Facilities Engineering Command  
P.O. Box 190010  
North Charleston, South Carolina 29419-9010

RE: Source Removal Report, Building 7107, Naval Training Center,  
Orlando, Florida


Dear Mr. Ugolini:

I have completed my review of the Source Removal Report and request for No Further Action for Building 7107, Naval Training Center, Orlando, dated June 1, 1999 (received June 3, 1999), prepared and submitted by Harding Lawson Associates. Before No Further Action can be approved for this site, some discrepancies in the report need to be resolved and additional information provided.



- (1) The area of excavation may be incorrectly drawn on Figure 2-1. The figure shows that locations E5 and F5 were not excavated. However, footnotes to the OVA results in Table 2-1 show that a composite sample taken from the backhoe bucket included locations E5 and F5.
- (2) I cannot reconcile Figure 2-1 and the stated number of yards transported for soil thermal treatment. The figure shows an excavated area approximately 13 feet by 14 feet. According to my calculations, that leaves only 1.3 feet depth of excavated material. The text states that the excavation was stopped at 7 feet below land surface.
- (3) The method used to collect samples for OVA measurement and the locations that are specific to each actual sample collected should be provided in the report. It appears that some samples were collected from a backhoe bucket, while others were not.
- (4) The exact location where microwell MC-1 was installed in relation to the soil excavation should be presented on a site diagram.

Mr. Nick Ugolini  
Source Removal Report, Bldg. 7107  
Naval Training Center, Orlando  
October 6, 1999  
Page two

If I can be of any further assistance with this matter,  
please contact me at (850) 488-3693.

Sincerely,  
  
David P. Grabka  
Remedial Project Manager

cc: Bill Bostwick, FDEP Central District Office  
Rick Allen, Harding Lawson Associates, Jacksonville  
Wayne Hansel, U.S. Navy, Southern Division  
Nancy Rodriguez, USEPA, Region 4  
Steve McCoy, Tetra Tech NUS, Oak Ridge, TN  
Alan Aiken, CH2M Hill, Orlando

TJB  JJC  ESN 